

MEETING MINUTES Reference No. 038443-62-03

PROJECT: South Dayton Dump & Landfill - Vapor Intrustion Mitigation

RE: Weekly Status Call

LOCATION: Teleconference DATE: July 24, 2014 TIME: 2:30 pm ET

Participants:

Steve Renninger	USEPA	Maddie Smith	Ohio EPA	
Lauren Foster	Tetra-Tech	Jim Campbell	ITW	
Wendell Barner	TRW	Adam Loney	CRA	
Valerie Chan	CRA			

Distribution:

⊠ File	⊠ Participants	Ken Brown, ITW	Tom Hut, PHDMC
Leslie Patterson, USEPA		Bryan Heath, NCR	

Item	Description	
1	Roll Call	
2	2 Status of Property Access:	
	☐ No additional mitigation work has been completed due to prohibited Site access to properties owned by the South Dayton Remediation Trust.	USEPA
	☐ The lawyers for the Respondents and South Dayton Remediation Trust have discussed the issue regarding access. The lawyers for the Respondents are preparing letters summarizing the available information to be distributed to the tenants and South Dayton Remediation Trust. In the letters, the South Dayton Remediation Trust and tenants will be presented with the choice to complete additional mitigation work or proceed with indoor air proficiency sampling only.	
	☐ USEPA requested a copy of a letter to review prior to finalization. CRA will provide a draft to USEPA.	
3	3 VI Mitigation Status:	
	☐ In Buildings 8 and 9 (B&G Trucking), Building 12 (Overstreet Painting and S&J Precision), and Building 15 (SIM Trainer), sub-slab (SS) concentrations less than Ohio Department of Health (ODH) screening levels have not been achieved.	
	As a result, the Upgraded Indoor Air (IA) sampling plan will need to be strengthened, i.e., collect IA samples in rooms where samples from SS probes exceeded ODH levels; collect samples when no doors are open; revise and strengthen the Standard Operating Procedure.	
	☐ CRA noted that sampling may be required to be completed on weekends in response to USEPA's proposed Upgraded IA sampling plan.	
	USEPA requested that Upgraded IA sampling plan language be included in the previously-mentioned letter to the tenants and the South Dayton Remediation Trust.	

CRA 038443Misc-MtgMin-07-24-14 Page 1 of 2



Item	Item Description		
3	VI Mitigation Status: (cont'd.)		
	☐ Deliverable: CRA will provide a figure for each building (Buildings 8, 9, 12, and 15) with rationale for Upgraded IA sampling plan locations.		
	☐ Bldg 24 (Globe Equipment):		
	- Building 24 is not owned by the South Dayton Remediation Trust.		
	- 365-day proficiency sampling is scheduled for August 21,2014.		
	- USEPA will collect split samples.		
	- Deliverable – Provide USEPA with map of Building 24 proficiency sample locations.		
4	Methane Monitoring:		
	☐ 1.1 to 1.7% methane was measured at GP-2, less than the trigger condition for increased monitoring		
	U 0% methane was measured in Building 15 (SIM Trainer).		
	☐ The values of methane were lower in the charcoal filtered readings than the non-filtered readings, indicating chlorinated solvents are involved in the chemical make-up.		
	☐ Deliverable – Redistribute the Draft Utility Corridor sampling addendum to USEPA		
5	Next steps/Other Business:	USEPA /	
	☐ Next Call: August 7, 2014 at 2:30 PM ET/1:30 PM CT.	CRA	
	☐ All parties agree to keep bi-weekly conference call schedule.		
Att	achments:		
Prepar	ed By: Valerie Chan Date Issued: August 7, 20		

This confirms and records CRA's interpretation of the discussions which occurred and our understanding reached during this meeting. Unless notified in writing within 7 days of the date issued, we will assume that this recorded interpretation or description is complete and accurate.

CRA 038443Misc-MtgMin-07-24-14 Page 2 of 2